	-	own of Essex Board of Appea Avenue, Essex, CT 06426 Ariance Application	IS (14 DEC
Date received b			√# 256 50 + State fee - \$60 = \$110 Pd. <u>√</u>
	23-18		
Premises: Stree	t Address _13 Novelty Lane		
Assessor's Map	# 50 Lot #005	Lot Area3.0	5ac
Zoning District	WF	Deed Reference: Bo	ook 0147 Page 0753
Owner of Prope	ertyEssex Yacht Club Inc	:	
Address13	Novelty Lane Essex CT 0642 Town	26 State Zip	
Telephone_860- home	767-8121Ema work	il: B.Forbes@essexyc.com	
	t owner)Paul Riggio /	Richard Riggio and Sons	
Applicant (if no		n CT 06442	
	Pond Meadow Road Ivoryto		
	Pond Meadow Road Ivoryton Town	State	Zip
Address90 Street TelephoneW Note:		0-662-0157 Email Paul@Ric	hardRiggioandsons.com

Si	ignature (Autho	rized Agent) <u><i>Paul</i></u>	Date	10 -23-23
Is Is	the property w	e property Property within 500' of another ithin the Gateway Conservation is for a variance(s) please comp	District? Yes	Other No
1.		equested of the Essex Zoning Reg t apply and write in sections that vari		
	Section No.	Allowed/Required per the regulations	Existing	Requested
2,	✓ <u>101E</u> ✓ <u>40D</u> □ <u>40F</u>	<u>A</u> variance requested of Sect No improvements except in co	tion 101E Gateway Buffer Ar onformity For Carcy for Con	ea for m

(Please attach supplemental sheets if space provided is insufficient)

Yes No 1a). Is a variance requested of Section 101E Gateway Buffer Area? If yes, the application shall be reviewed by the Essex Inland Wetlands and Watercourses Commission (per Section 140L) and a letter of referral shall be provided by the EIWWC prior to attending the ZBA meeting.

2. Variance is requested to allow (Please describe proposed use, dimensions, height and location of any new construction PLUS any changes to use, size, shape, bulk, footprint, floor area or height of existing structure)

Please see the plans attached to the application for all measurement The proposed use is the addition of an elevator shaft to allow for access to the second floor of the building for handicap persons (Please attach supplemental sheets if space provided is insufficient)

3. Strict application of Essex Zoning Regulations would result in an unusual hardship because of the following characteristics of the property (Support topological hardship claims with photographs, survey, etc.)

a. The membership of the Essex Yacht Club voted to support the addition of an elevator for the aging and in need members. There is no reasonable location in the interior of the building to place an elevator without greatly effecting the function of the interior. Due to the structural design of the original floor structure it would be nearly impossible to cut through this 3" plank deck floor to the second floor and support as needed. The engineer thought an exterior addition was the best solution to this problem. Adding an elevator is the responsible thing to do.

b._____ c.____

4. The above hardship is unique to this parcel and not shared by other in the area because:

a. <u>Due to the current location of this building there is no choice but to construct this addition in the requested</u> <u>location. The only area of the existing building high enough to make a two floor elevator work is in this</u> <u>location. Please refer to the plans to see how tight the design is.</u>

b. Due to the unstable ground, all of the Essex Yacht Club's main building is built on pilings and grade beams. It would be impossible to drive pilings within the existing building to support this additional structural load. Therefore the only location for this elevator can be on the outside of the existing building

C. Why was this location picked? As access is needed to the elevator on both the first and second floors, there are only two locations on the exterior of this building to put the elevator that is high enough for the elevator to work. One location is the south side of the building. We chose not to use this location due to

the visual issue from the CT River. The north side was picked as it would tuck in behind the deck and would be less visible. The second question might be, why not inside the existing build? As stated above "Due to the unstable ground, all of the Essex Yacht Club's main building is built on pilings and grade beams. It would be impossible to drive pilings within the existing building to support this additional structure ".The conclusion was that this location would have the least visual impact to the surrounding properties and take care of the need for the elevator.

D. Described proposed reductions in legal pre-existing nonconformities, if any

а.			
b.			
<u>c</u> .			

.

The requested variance(s) are in harmony with the purpose and intent of Essex Zoning Regulations because:

<u>a</u>.

We believe the requested variance is in harmony with the intent of the Zoning regulations as this elevator addition was designed with the smallest footprint possible to provide for a much needed elevator. An elevator is a need, not a luxury!

<u>b.</u>	
с.	
	For Carey to Confirm
Have previous applications been made for this property?	
If yes, previous application #s Date	
Prior variance request:	Variance Board Action

The following items must be included as part of this application:

~	a. Fee of \$110.00 -	- Town Fee \$50	plus \$60 S	tate Feepayable to	o the Town of Essex

- ____ b. 10 copies of the application, site plan (with setback lines) and sketch of the proposal.
- _____ c. Copy of property deed
- d. Referral from Health Department
- _____e. Referral from Essex IWWC (if applicable)
- _____f. Referral from adjacent towns
- g. Referral from Gateway Conservation Commission
 - h. Referral from the Essex Harbor Management Commission

Owner/Applicant Commitments

I (we) certify that the statements hereinabove made and the documents submitted herewith are true to the best of my (our) knowledge and belief.

I (we) consent to allow Zoning Board of Appeals members access to the property for informal, independent site visits, for the purpose of evaluating this application prior to the Board rendering its decision.

Signature of applicant Land Ragio	Date:	<u>10 -23-</u> 23
Signature of property owner Essex Yorcht Club	Date:	10-23-23
by Devor Dreson f. House Connective Chroix		

Applicant must provide a current list of all names and addresses of abutting property owners.

NAMEADDRESSTOWNZIP CODESHM Dauntless LLC_14785 Preston Rd STE 975Dallas,TX_7 5254_Bowers William & Kennedy Joanne (jt) 15 Novelty Lane Essex, CT 06426_

1.00



